eBeam® Quick Setup Guide

1. Turn on the projector
2. Turn on the laptop
3. Connect the eBeam USB cable to your laptop USB port
4. Connect the VGA port to the laptop

5. Press e-Beam power button from the Console.
6. To sync the laptop with e-Beam, press Calibrate button from the console. Click the stylus on the targets in the projected area showing on the whiteboard.

7. On the stylus,

Press the round button to show the tool palette.